



7655 Convoy Court  
 San Diego CA 92111  
 1.800.891.4822  
 Phone: 858.974.6500  
 Fax: 858.974.6501

1701 East Edinger Ave. Suite F-4  
 Santa Ana CA 92705  
 1.800.891.4822  
 Phone: 714.285.2600  
 Fax: 714.285.2601

CA License No.: 814462

**Call Summary 2011-1053**

**Work Order Information**

<b>Location:</b>	Pacific Rim Mechanical 7655 Convoy Court San Diego CA 92111	<b>Primary Technician:</b>	Scott, Tyler
		<b>Technician Team:</b>	SD SERVICE 1
		<b>Call Type:</b>	Time Material

<b>Contact:</b>	Valerie McGuire (000) 000-0000 x0000	<b>Customer Bill To:</b>	Pacific Rim Mechanical 7655 Convoy Court San Diego CA 92111
<b>Caller:</b>	Brett Ludwick		
<b>P.O. #:</b>			

**Technician Recommendations**

If this Service Call contains any recommendations you will see a URL in the Resolution Notes below.  
 Example: <https://vision.xoeeye>  
 The URL should be opened with Google Chrome for best results.

**Service Description**

<b>Description</b>	Bldg A HP-6 not operating properly Brett Ludwick / JC
--------------------	---

**Resolution**

This Work Order Is Complete  
 [11/16/2020 10:45:23 AM Scott, Tyler]  
 Arrived at site, checked in with customer, accessed roof, and located HP-6. During troubleshooting, found that the indoor blower drive belt had broken, inhibiting operation of the blower. Drive belt will need to be replaced. Following my inspection, I also noticed the evaporator condensate pan is dirty and should be cleaned, the air filter is incorrectly sized and should be replaced with one of the correct size, and there is a substantial amount of oil accumulation on the liquid line filter drier, which is a telltale indication of a refrigerant leak. The refrigerant will be tested for leaks and repaired accordingly. Proposal for all aforementioned repairs will be submitted. Cleaned up work area and left site.

**Click the URL!**

Please use the following URL to view related photos/videos:  
<https://visionshare.xoi.io/?id=ws2c7b02cd-7c1a-49c8-aa5f-cacc79552e21>